

| CAR HIRE DEPRESCRIPTION DEFAULT RATES: 2024 Q4            |        |         |        |         |     |
|-----------------------------------------------------------|--------|---------|--------|---------|-----|
| FOR CARS ADDED TO UMLER FROM 10/1/2024 TO 12/30/2024      |        |         |        |         |     |
| BASED ON NEGOTIATED RATES EFFECTIVE 09/30/2024            |        |         |        |         |     |
| Please Refer to OT-10, Appendix T for Appurtenance Values |        |         |        |         |     |
| CAR                                                       | LOADED | LOADED  | EMPTY  | EMPTY   | NEG |
| TYPE                                                      | HOURLY | MILEAGE | HOURLY | MILEAGE | PRE |
| CODE                                                      | RATE   | RATE    | RATE   | RATE    | IND |
| A                                                         | 0.050  | 0.045   | 0.040  | 0.045   | N   |
| A3                                                        | 0.280  | 0.045   | 0.040  | 0.045   | N   |
| A30                                                       | 0.280  | 0.045   | 0.040  | 0.045   | N   |
| A300                                                      | 0.500  | 0.060   | 0.500  | 0.060   | N   |
| A302                                                      | 0.280  | 0.000   | 0.040  | 0.060   | N   |
| A303                                                      | 0.300  | 0.045   | 0.300  | 0.045   | N   |
| A305                                                      | 0.480  | 0.050   | 0.480  | 0.050   | N   |
| A306                                                      | 0.500  | 0.050   | 0.500  | 0.050   | N   |
| A307                                                      | 0.650  | 0.065   | 0.650  | 0.065   | N   |
| A31                                                       | 0.500  | 0.063   | 0.500  | 0.063   | N   |
| A312                                                      | 0.500  | 0.063   | 0.500  | 0.063   | N   |
| A33                                                       | 0.280  | 0.063   | 0.170  | 0.063   | N   |
| A332                                                      | 0.280  | 0.000   | 0.170  | 0.067   | N   |
| A335                                                      | 0.500  | 0.063   | 0.500  | 0.063   | N   |
| A4                                                        | 0.050  | 0.047   | 0.080  | 0.047   | N   |
| A40                                                       | 0.050  | 0.049   | 0.080  | 0.049   | N   |
| A400                                                      | 0.530  | 0.060   | 0.530  | 0.060   | N   |
| A402                                                      | 0.280  | 0.000   | 0.170  | 0.075   | N   |
| A403                                                      | 0.330  | 0.050   | 0.170  | 0.074   | N   |
| A405                                                      | 0.050  | 0.067   | 0.080  | 0.060   | N   |
| A406                                                      | 0.170  | 0.049   | 0.170  | 0.049   | N   |
| A407                                                      | 0.500  | 0.050   | 0.500  | 0.050   | N   |
| A41                                                       | 0.470  | 0.047   | 0.470  | 0.047   | N   |
| A413                                                      | 0.700  | 0.060   | 0.700  | 0.060   | N   |
| A416                                                      | 0.470  | 0.047   | 0.470  | 0.047   | N   |
| A43                                                       | 0.280  | 0.050   | 0.170  | 0.050   | N   |
| A432                                                      | 0.410  | 0.060   | 0.170  | 0.060   | N   |
| A433                                                      | 0.500  | 0.050   | 0.170  | 0.074   | N   |
| A435                                                      | 0.280  | 0.000   | 0.170  | 0.070   | N   |
| A436                                                      | 0.500  | 0.050   | 0.500  | 0.050   | N   |
| A44                                                       | 0.500  | 0.050   | 0.500  | 0.050   | N   |
| A446                                                      | 0.500  | 0.050   | 0.500  | 0.050   | N   |
| A5                                                        | 0.650  | 0.060   | 0.650  | 0.060   | N   |
| A50                                                       | 0.650  | 0.060   | 0.650  | 0.060   | N   |
| A502                                                      | 0.650  | 0.070   | 0.650  | 0.070   | N   |
| A506                                                      | 0.720  | 0.060   | 0.720  | 0.060   | N   |
| A507                                                      | 0.700  | 0.065   | 0.700  | 0.065   | N   |
| A6                                                        | 0.170  | 0.049   | 0.170  | 0.049   | N   |
| A60                                                       | 0.170  | 0.049   | 0.170  | 0.060   | N   |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| A602 | 0.280 | 0.000 | 0.280 | 0.000 | N |
| A603 | 0.500 | 0.060 | 0.500 | 0.060 | N |
| A605 | 0.280 | 0.000 | 0.280 | 0.000 | N |
| A606 | 0.170 | 0.049 | 0.170 | 0.073 | N |
| A61  | 0.730 | 0.070 | 0.730 | 0.070 | N |
| A616 | 0.730 | 0.070 | 0.730 | 0.070 | N |
| A63  | 0.190 | 0.049 | 0.170 | 0.049 | N |
| A632 | 0.280 | 0.000 | 0.170 | 0.072 | N |
| A633 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| A635 | 0.550 | 0.080 | 0.550 | 0.080 | N |
| A636 | 0.190 | 0.049 | 0.170 | 0.049 | N |
| A64  | 0.600 | 0.060 | 0.600 | 0.060 | N |
| A646 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| A8   | 0.700 | 0.060 | 0.700 | 0.060 | N |
| A80  | 0.700 | 0.060 | 0.700 | 0.060 | N |
| A806 | 0.700 | 0.060 | 0.700 | 0.060 | N |
| A81  | 0.750 | 0.070 | 0.750 | 0.070 | N |
| A816 | 0.750 | 0.070 | 0.750 | 0.070 | N |
| A83  | 0.700 | 0.060 | 0.700 | 0.060 | N |
| A836 | 0.700 | 0.060 | 0.700 | 0.060 | N |
| B    | 0.430 | 0.045 | 0.430 | 0.045 | N |
| B3   | 0.430 | 0.045 | 0.430 | 0.045 | N |
| B30  | 0.450 | 0.045 | 0.450 | 0.045 | N |
| B304 | 0.450 | 0.045 | 0.450 | 0.045 | N |
| B305 | 0.530 | 0.060 | 0.530 | 0.060 | N |
| B31  | 0.430 | 0.053 | 0.430 | 0.055 | N |
| B314 | 0.430 | 0.053 | 0.430 | 0.059 | N |
| B317 | 0.580 | 0.055 | 0.580 | 0.055 | N |
| B33  | 0.580 | 0.055 | 0.580 | 0.055 | N |
| B334 | 0.580 | 0.055 | 0.580 | 0.055 | N |
| B4   | 0.450 | 0.045 | 0.450 | 0.045 | N |
| B41  | 0.450 | 0.045 | 0.450 | 0.045 | N |
| B414 | 0.450 | 0.045 | 0.450 | 0.045 | N |
| B415 | 0.540 | 0.060 | 0.540 | 0.060 | N |
| B417 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| B43  | 0.680 | 0.060 | 0.680 | 0.060 | N |
| B435 | 0.740 | 0.065 | 0.740 | 0.065 | N |
| B437 | 0.680 | 0.060 | 0.680 | 0.060 | N |
| B6   | 0.550 | 0.060 | 0.550 | 0.060 | N |
| B61  | 0.800 | 0.070 | 0.800 | 0.070 | N |
| B617 | 0.800 | 0.070 | 0.800 | 0.070 | N |
| B62  | 0.550 | 0.060 | 0.550 | 0.060 | N |
| B625 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| B627 | 0.550 | 0.080 | 0.550 | 0.080 | N |
| B63  | 0.550 | 0.065 | 0.550 | 0.065 | N |
| B634 | 0.780 | 0.065 | 0.780 | 0.065 | N |
| B635 | 0.550 | 0.080 | 0.550 | 0.080 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| B637 | 0.600 | 0.070 | 0.600 | 0.070 | N |
| C    | 0.050 | 0.040 | 0.050 | 0.040 | N |
| C1   | 0.050 | 0.050 | 0.050 | 0.050 | N |
| C11  | 0.050 | 0.050 | 0.050 | 0.050 | N |
| C111 | 0.400 | 0.050 | 0.400 | 0.050 | N |
| C112 | 0.050 | 0.077 | 0.050 | 0.077 | N |
| C113 | 0.350 | 0.050 | 0.290 | 0.062 | N |
| C114 | 0.490 | 0.065 | 0.490 | 0.065 | N |
| C2   | 0.900 | 0.075 | 0.900 | 0.075 | N |
| C21  | 0.900 | 0.075 | 0.900 | 0.075 | N |
| C214 | 0.900 | 0.075 | 0.900 | 0.075 | N |
| C3   | 0.450 | 0.040 | 0.450 | 0.040 | N |
| C31  | 0.450 | 0.040 | 0.450 | 0.040 | N |
| C313 | 0.450 | 0.040 | 0.450 | 0.040 | N |
| C314 | 0.550 | 0.065 | 0.550 | 0.065 | N |
| C4   | 0.600 | 0.075 | 0.600 | 0.075 | N |
| C41  | 0.600 | 0.075 | 0.600 | 0.075 | N |
| C413 | 0.600 | 0.075 | 0.600 | 0.075 | N |
| C6   | 0.730 | 0.070 | 0.730 | 0.070 | N |
| C61  | 0.730 | 0.070 | 0.730 | 0.070 | N |
| C614 | 0.730 | 0.070 | 0.730 | 0.070 | N |
| E    | 0.210 | 0.040 | 0.200 | 0.040 | N |
| E1   | 0.250 | 0.040 | 0.250 | 0.040 | N |
| E10  | 0.250 | 0.040 | 0.250 | 0.040 | N |
| E104 | 0.620 | 0.070 | 0.620 | 0.070 | N |
| E105 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E106 | 0.250 | 0.040 | 0.250 | 0.040 | N |
| E11  | 0.310 | 0.050 | 0.310 | 0.050 | N |
| E114 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E115 | 0.310 | 0.064 | 0.310 | 0.064 | N |
| E13  | 0.600 | 0.060 | 0.600 | 0.060 | N |
| E131 | 0.600 | 0.083 | 0.600 | 0.083 | N |
| E134 | 0.700 | 0.060 | 0.700 | 0.060 | N |
| E14  | 0.380 | 0.083 | 0.380 | 0.083 | N |
| E141 | 0.600 | 0.083 | 0.600 | 0.083 | N |
| E142 | 0.380 | 0.117 | 0.380 | 0.117 | N |
| E2   | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E23  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E231 | 0.600 | 0.083 | 0.600 | 0.083 | N |
| E232 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E24  | 0.520 | 0.080 | 0.520 | 0.080 | N |
| E241 | 0.600 | 0.080 | 0.600 | 0.080 | N |
| E242 | 0.520 | 0.100 | 0.520 | 0.100 | N |
| E244 | 0.850 | 0.090 | 0.850 | 0.090 | N |
| E3   | 0.250 | 0.040 | 0.250 | 0.040 | N |
| E30  | 0.250 | 0.040 | 0.250 | 0.040 | N |
| E306 | 0.250 | 0.040 | 0.250 | 0.040 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| E307 | 0.580 | 0.060 | 0.580 | 0.060 | N |
| E33  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E331 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E334 | 0.500 | 0.060 | 0.500 | 0.060 | N |
| E335 | 0.700 | 0.080 | 0.700 | 0.080 | N |
| E34  | 0.700 | 0.070 | 0.700 | 0.070 | N |
| E342 | 0.700 | 0.070 | 0.700 | 0.070 | N |
| E4   | 0.600 | 0.060 | 0.600 | 0.060 | N |
| E43  | 0.620 | 0.070 | 0.620 | 0.070 | N |
| E431 | 0.620 | 0.070 | 0.620 | 0.070 | N |
| E432 | 0.750 | 0.090 | 0.750 | 0.090 | N |
| E44  | 0.600 | 0.060 | 0.600 | 0.060 | N |
| E441 | 0.600 | 0.080 | 0.600 | 0.080 | N |
| E442 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| E444 | 0.720 | 0.080 | 0.720 | 0.080 | N |
| E5   | 0.210 | 0.050 | 0.200 | 0.050 | N |
| E50  | 0.600 | 0.085 | 0.600 | 0.085 | N |
| E507 | 0.600 | 0.085 | 0.600 | 0.085 | N |
| E52  | 0.500 | 0.104 | 0.500 | 0.104 | N |
| E524 | 0.500 | 0.104 | 0.500 | 0.104 | N |
| E53  | 0.210 | 0.050 | 0.210 | 0.050 | N |
| E531 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E534 | 0.210 | 0.058 | 0.210 | 0.058 | N |
| E535 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E536 | 0.620 | 0.070 | 0.620 | 0.070 | N |
| E54  | 0.480 | 0.050 | 0.200 | 0.050 | N |
| E541 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| E542 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| E544 | 0.600 | 0.085 | 0.200 | 0.058 | N |
| E58  | 0.480 | 0.050 | 0.480 | 0.050 | N |
| E584 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| E6   | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E62  | 0.700 | 0.060 | 0.700 | 0.060 | N |
| E624 | 0.700 | 0.060 | 0.700 | 0.060 | N |
| E63  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E631 | 0.620 | 0.070 | 0.620 | 0.070 | N |
| E634 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E64  | 0.500 | 0.056 | 0.500 | 0.056 | N |
| E641 | 0.590 | 0.070 | 0.590 | 0.070 | N |
| E642 | 0.500 | 0.056 | 0.500 | 0.056 | N |
| E644 | 0.650 | 0.090 | 0.650 | 0.090 | N |
| E7   | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E70  | 0.600 | 0.085 | 0.600 | 0.085 | N |
| E707 | 0.600 | 0.085 | 0.600 | 0.085 | N |
| E71  | 0.650 | 0.080 | 0.650 | 0.080 | N |
| E717 | 0.650 | 0.080 | 0.650 | 0.080 | N |
| E73  | 0.500 | 0.050 | 0.500 | 0.050 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| E731 | 0.630 | 0.104 | 0.630 | 0.104 | N |
| E734 | 0.570 | 0.060 | 0.570 | 0.060 | N |
| E735 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| E74  | 0.650 | 0.065 | 0.650 | 0.065 | N |
| E745 | 0.650 | 0.065 | 0.650 | 0.065 | N |
| E8   | 0.500 | 0.090 | 0.500 | 0.090 | N |
| E83  | 0.500 | 0.090 | 0.500 | 0.090 | N |
| E835 | 0.500 | 0.090 | 0.500 | 0.090 | N |
| F    | 0.077 | 0.027 | 0.077 | 0.027 | N |
| F1   | 0.290 | 0.027 | 0.290 | 0.027 | N |
| F10  | 0.420 | 0.066 | 0.420 | 0.066 | N |
| F103 | 0.420 | 0.066 | 0.420 | 0.066 | N |
| F12  | 0.290 | 0.027 | 0.290 | 0.027 | N |
| F123 | 0.420 | 0.066 | 0.420 | 0.066 | N |
| F126 | 0.290 | 0.027 | 0.290 | 0.027 | N |
| F14  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F141 | 0.550 | 0.055 | 0.550 | 0.055 | N |
| F142 | 0.500 | 0.054 | 0.500 | 0.054 | N |
| F144 | 0.660 | 0.050 | 0.660 | 0.050 | N |
| F15  | 0.550 | 0.055 | 0.550 | 0.055 | N |
| F151 | 0.550 | 0.055 | 0.550 | 0.055 | N |
| F17  | 0.500 | 0.054 | 0.500 | 0.054 | N |
| F172 | 0.500 | 0.054 | 0.500 | 0.054 | N |
| F18  | 0.550 | 0.050 | 0.550 | 0.050 | N |
| F181 | 0.550 | 0.050 | 0.550 | 0.050 | N |
| F2   | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F20  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F203 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F206 | 0.590 | 0.057 | 0.590 | 0.057 | N |
| F22  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F222 | 0.520 | 0.060 | 0.520 | 0.060 | N |
| F223 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F226 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F24  | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F241 | 0.550 | 0.055 | 0.550 | 0.055 | N |
| F242 | 0.500 | 0.056 | 0.500 | 0.056 | N |
| F243 | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F25  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F251 | 0.500 | 0.055 | 0.500 | 0.055 | N |
| F252 | 0.500 | 0.051 | 0.500 | 0.051 | N |
| F253 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F255 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F256 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F27  | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F272 | 0.500 | 0.057 | 0.500 | 0.057 | N |
| F273 | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F28  | 0.550 | 0.050 | 0.550 | 0.050 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| F281 | 0.550 | 0.050 | 0.550 | 0.050 | N |
| F283 | 0.720 | 0.060 | 0.720 | 0.060 | N |
| F3   | 0.077 | 0.040 | 0.077 | 0.040 | N |
| F30  | 0.500 | 0.057 | 0.500 | 0.057 | N |
| F302 | 0.500 | 0.057 | 0.500 | 0.057 | N |
| F303 | 0.700 | 0.060 | 0.700 | 0.060 | N |
| F31  | 0.650 | 0.060 | 0.650 | 0.060 | N |
| F313 | 0.650 | 0.060 | 0.650 | 0.060 | N |
| F32  | 0.420 | 0.051 | 0.420 | 0.051 | N |
| F323 | 0.420 | 0.051 | 0.420 | 0.051 | N |
| F326 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| F34  | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F341 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| F342 | 0.500 | 0.056 | 0.500 | 0.056 | N |
| F343 | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F35  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F351 | 0.640 | 0.065 | 0.640 | 0.065 | N |
| F353 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F355 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F37  | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F372 | 0.500 | 0.056 | 0.500 | 0.056 | N |
| F373 | 0.500 | 0.040 | 0.500 | 0.040 | N |
| F38  | 0.077 | 0.060 | 0.077 | 0.060 | N |
| F383 | 0.077 | 0.060 | 0.077 | 0.060 | N |
| F384 | 0.750 | 0.060 | 0.750 | 0.060 | N |
| F4   | 0.300 | 0.050 | 0.300 | 0.050 | N |
| F40  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F403 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F405 | 2.250 | 0.100 | 2.250 | 0.100 | N |
| F41  | 0.420 | 0.060 | 0.420 | 0.060 | N |
| F411 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| F413 | 0.650 | 0.060 | 0.650 | 0.060 | N |
| F42  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F421 | 0.540 | 0.060 | 0.540 | 0.060 | N |
| F422 | 0.540 | 0.060 | 0.540 | 0.060 | N |
| F423 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F426 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| F43  | 2.700 | 0.100 | 2.700 | 0.100 | N |
| F431 | 2.700 | 0.100 | 2.700 | 0.100 | N |
| F432 | 3.800 | 0.120 | 3.800 | 0.120 | N |
| F433 | 5.000 | 0.150 | 5.000 | 0.150 | N |
| F434 | 3.800 | 0.120 | 3.800 | 0.120 | N |
| F435 | 3.800 | 0.120 | 3.800 | 0.120 | N |
| F44  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F441 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F443 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F444 | 0.850 | 0.060 | 0.850 | 0.060 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| F45  | 0.420 | 0.060 | 0.420 | 0.060 | N |
| F451 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| F452 | 0.750 | 0.060 | 0.750 | 0.060 | N |
| F453 | 0.500 | 0.060 | 0.500 | 0.060 | N |
| F454 | 0.550 | 0.060 | 0.550 | 0.060 | N |
| F48  | 0.300 | 0.050 | 0.300 | 0.050 | N |
| F481 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| F483 | 0.300 | 0.060 | 0.300 | 0.060 | N |
| F484 | 0.650 | 0.055 | 0.650 | 0.055 | N |
| F49  | 0.700 | 0.061 | 0.700 | 0.061 | N |
| F493 | 0.700 | 0.061 | 0.700 | 0.061 | N |
| G    | 0.300 | 0.050 | 0.300 | 0.050 | N |
| G1   | 0.380 | 0.050 | 0.380 | 0.050 | N |
| G11  | 0.380 | 0.050 | 0.380 | 0.050 | N |
| G112 | 0.550 | 0.055 | 0.550 | 0.055 | N |
| G114 | 0.380 | 0.117 | 0.380 | 0.117 | N |
| G116 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G118 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G119 | 0.550 | 0.055 | 0.550 | 0.055 | N |
| G12  | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G122 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G2   | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G21  | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G219 | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G3   | 0.450 | 0.050 | 0.450 | 0.050 | N |
| G31  | 0.450 | 0.050 | 0.450 | 0.050 | N |
| G314 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| G318 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| G4   | 0.770 | 0.095 | 0.770 | 0.095 | N |
| G41  | 0.770 | 0.095 | 0.770 | 0.095 | N |
| G413 | 0.770 | 0.095 | 0.770 | 0.095 | N |
| G5   | 0.300 | 0.050 | 0.300 | 0.050 | N |
| G51  | 0.300 | 0.050 | 0.300 | 0.050 | N |
| G510 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G512 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G513 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| G514 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G515 | 0.450 | 0.000 | 0.450 | 0.000 | N |
| G516 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G517 | 0.580 | 0.055 | 0.580 | 0.055 | N |
| G518 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| G519 | 0.300 | 0.100 | 0.300 | 0.100 | N |
| G52  | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G520 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G522 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G525 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| G53  | 0.600 | 0.060 | 0.600 | 0.060 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| G535 | 0.600 | 0.085 | 0.600 | 0.085 | N |
| G538 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| G7   | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G71  | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G712 | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G716 | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G717 | 0.570 | 0.060 | 0.570 | 0.060 | N |
| G719 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| G73  | 0.590 | 0.070 | 0.590 | 0.070 | N |
| G736 | 0.590 | 0.070 | 0.590 | 0.070 | N |
| H    | 0.350 | 0.040 | 0.350 | 0.040 | N |
| H2   | 0.480 | 0.050 | 0.480 | 0.050 | N |
| H25  | 0.480 | 0.050 | 0.480 | 0.050 | N |
| H250 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| H3   | 0.350 | 0.040 | 0.350 | 0.040 | N |
| H33  | 0.500 | 0.069 | 0.500 | 0.069 | N |
| H330 | 0.500 | 0.069 | 0.500 | 0.069 | N |
| H34  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| H340 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| H35  | 0.350 | 0.040 | 0.350 | 0.040 | N |
| H350 | 0.350 | 0.040 | 0.350 | 0.040 | N |
| H351 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| H352 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| J    | 0.200 | 0.020 | 0.200 | 0.020 | N |
| J3   | 0.200 | 0.020 | 0.200 | 0.020 | N |
| J30  | 0.200 | 0.020 | 0.200 | 0.020 | N |
| J300 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| J301 | 0.200 | 0.020 | 0.200 | 0.020 | N |
| J302 | 0.600 | 0.090 | 0.600 | 0.090 | N |
| J303 | 0.500 | 0.078 | 0.500 | 0.078 | N |
| J304 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| J31  | 0.410 | 0.065 | 0.410 | 0.065 | N |
| J311 | 0.410 | 0.070 | 0.410 | 0.070 | N |
| J312 | 0.550 | 0.065 | 0.550 | 0.065 | N |
| K    | 0.420 | 0.050 | 0.420 | 0.050 | N |
| K1   | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K14  | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K147 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K2   | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K24  | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K247 | 0.450 | 0.050 | 0.450 | 0.050 | N |
| K3   | 0.420 | 0.050 | 0.420 | 0.050 | N |
| K30  | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K304 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K32  | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K324 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K327 | 0.420 | 0.064 | 0.420 | 0.064 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| K34  | 0.420 | 0.050 | 0.420 | 0.050 | N |
| K341 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| K342 | 0.500 | 0.110 | 0.500 | 0.110 | N |
| K344 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K345 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K346 | 0.450 | 0.070 | 0.450 | 0.070 | N |
| K347 | 0.420 | 0.064 | 0.420 | 0.064 | N |
| K38  | 0.500 | 0.084 | 0.500 | 0.084 | N |
| K384 | 0.500 | 0.084 | 0.500 | 0.084 | N |
| L    | 0.480 | 0.050 | 0.480 | 0.050 | N |
| L0   | 0.480 | 0.050 | 0.480 | 0.050 | N |
| L02  | 0.480 | 0.050 | 0.480 | 0.050 | N |
| L026 | 0.480 | 0.050 | 0.480 | 0.050 | N |
| L027 | 0.550 | 0.050 | 0.550 | 0.050 | N |
| P    | 0.280 | 0.009 | 0.280 | 0.009 | P |
| P3   | 0.580 | 0.009 | 0.580 | 0.009 | P |
| P38  | 0.580 | 0.009 | 0.580 | 0.009 | P |
| P381 | 0.580 | 0.009 | 0.580 | 0.009 | P |
| P4   | 0.460 | 0.035 | 0.460 | 0.035 | P |
| P43  | 0.460 | 0.035 | 0.460 | 0.035 | P |
| P435 | 0.460 | 0.035 | 0.460 | 0.035 | P |
| P7   | 0.430 | 0.035 | 0.430 | 0.035 | P |
| P71  | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P712 | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P72  | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P720 | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P721 | 1.300 | 0.044 | 1.300 | 0.044 | P |
| P722 | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P73  | 0.450 | 0.037 | 0.450 | 0.037 | P |
| P732 | 0.450 | 0.037 | 0.450 | 0.037 | P |
| P74  | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P741 | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P75  | 0.590 | 0.035 | 0.590 | 0.035 | P |
| P751 | 0.590 | 0.035 | 0.590 | 0.035 | P |
| P78  | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P781 | 0.450 | 0.037 | 0.450 | 0.037 | P |
| P782 | 0.430 | 0.037 | 0.430 | 0.037 | P |
| P8   | 0.280 | 0.020 | 0.280 | 0.020 | P |
| P84  | 0.280 | 0.038 | 0.280 | 0.038 | P |
| P841 | 0.450 | 0.038 | 0.450 | 0.038 | P |
| P842 | 0.280 | 0.061 | 0.280 | 0.061 | P |
| P85  | 0.630 | 0.042 | 0.630 | 0.042 | P |
| P852 | 0.630 | 0.042 | 0.630 | 0.042 | P |
| P87  | 0.410 | 0.020 | 0.410 | 0.020 | P |
| P873 | 0.410 | 0.020 | 0.410 | 0.020 | P |
| P88  | 0.450 | 0.037 | 0.450 | 0.037 | P |
| P882 | 0.450 | 0.037 | 0.450 | 0.037 | P |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| Q    | 1.040 | 0.073 | 1.040 | 0.073 | N |
| Q5   | 1.040 | 0.073 | 1.040 | 0.073 | N |
| Q52  | 1.040 | 0.073 | 1.040 | 0.073 | N |
| Q520 | 1.040 | 0.073 | 1.040 | 0.073 | N |
| R    | 0.500 | 0.050 | 0.500 | 0.050 | N |
| R3   | 0.570 | 0.065 | 0.500 | 0.050 | N |
| R30  | 0.570 | 0.065 | 0.500 | 0.050 | N |
| R300 | 0.570 | 0.065 | 0.500 | 0.050 | N |
| R37  | 0.700 | 0.080 | 0.700 | 0.080 | N |
| R370 | 0.700 | 0.080 | 0.700 | 0.080 | N |
| R4   | 0.500 | 0.050 | 0.500 | 0.050 | N |
| R40  | 0.500 | 0.050 | 0.500 | 0.050 | N |
| R400 | 0.500 | 0.050 | 0.500 | 0.050 | N |
| R41  | 0.570 | 0.065 | 0.500 | 0.050 | N |
| R410 | 0.570 | 0.065 | 0.500 | 0.050 | N |
| R47  | 0.700 | 0.080 | 0.700 | 0.080 | N |
| R470 | 0.700 | 0.080 | 0.700 | 0.080 | N |
| R5   | 0.600 | 0.060 | 0.600 | 0.060 | N |
| R50  | 0.600 | 0.060 | 0.600 | 0.060 | N |
| R500 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| R6   | 0.500 | 0.060 | 0.500 | 0.060 | N |
| R60  | 0.500 | 0.063 | 0.500 | 0.063 | N |
| R600 | 0.500 | 0.063 | 0.500 | 0.063 | N |
| R61  | 0.550 | 0.060 | 0.550 | 0.060 | N |
| R610 | 0.550 | 0.060 | 0.550 | 0.060 | N |
| R66  | 1.710 | 0.134 | 1.710 | 0.134 | N |
| R660 | 1.710 | 0.134 | 1.710 | 0.134 | N |
| S    | 0.350 | 0.015 | 0.350 | 0.015 | N |
| S1   | 0.590 | 0.021 | 0.590 | 0.021 | N |
| S11  | 0.590 | 0.021 | 0.590 | 0.021 | N |
| S115 | 0.590 | 0.021 | 0.590 | 0.021 | N |
| S13  | 1.700 | 0.050 | 1.700 | 0.050 | N |
| S136 | 2.650 | 0.080 | 2.650 | 0.080 | N |
| S138 | 1.700 | 0.050 | 1.700 | 0.050 | N |
| S16  | 1.350 | 0.060 | 1.350 | 0.060 | N |
| S161 | 2.750 | 0.078 | 2.750 | 0.078 | N |
| S162 | 1.350 | 0.060 | 1.350 | 0.060 | N |
| S167 | 2.650 | 0.085 | 2.650 | 0.085 | N |
| S169 | 2.750 | 0.078 | 2.750 | 0.078 | N |
| S17  | 1.850 | 0.068 | 1.850 | 0.068 | N |
| S170 | 1.850 | 0.068 | 1.850 | 0.068 | N |
| S172 | 1.850 | 0.068 | 1.850 | 0.068 | N |
| S174 | 1.850 | 0.070 | 1.850 | 0.070 | N |
| S175 | 1.850 | 0.071 | 1.850 | 0.071 | N |
| S178 | 1.850 | 0.071 | 1.850 | 0.071 | N |
| S3   | 0.510 | 0.015 | 0.510 | 0.015 | N |
| S31  | 0.510 | 0.015 | 0.510 | 0.015 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| S310 | 0.670 | 0.019 | 0.670 | 0.019 | N |
| S312 | 0.580 | 0.020 | 0.580 | 0.020 | N |
| S313 | 0.510 | 0.015 | 0.510 | 0.015 | N |
| S33  | 1.690 | 0.050 | 1.690 | 0.050 | N |
| S332 | 1.700 | 0.050 | 1.700 | 0.050 | N |
| S333 | 1.690 | 0.050 | 1.690 | 0.050 | N |
| S34  | 2.750 | 0.080 | 2.750 | 0.080 | N |
| S342 | 2.750 | 0.080 | 2.750 | 0.080 | N |
| S35  | 2.750 | 0.080 | 2.750 | 0.080 | N |
| S350 | 2.750 | 0.080 | 2.750 | 0.080 | N |
| S36  | 2.330 | 0.065 | 2.330 | 0.065 | N |
| S364 | 2.330 | 0.105 | 2.330 | 0.105 | N |
| S367 | 2.350 | 0.080 | 2.350 | 0.080 | N |
| S368 | 2.500 | 0.065 | 2.500 | 0.065 | N |
| S4   | 1.950 | 0.080 | 1.950 | 0.080 | N |
| S45  | 1.950 | 0.080 | 1.950 | 0.080 | N |
| S450 | 1.950 | 0.080 | 1.950 | 0.080 | N |
| S6   | 0.350 | 0.021 | 0.350 | 0.021 | N |
| S61  | 0.350 | 0.021 | 0.350 | 0.021 | N |
| S615 | 0.350 | 0.000 | 0.350 | 0.000 | N |
| S619 | 0.630 | 0.021 | 0.630 | 0.021 | N |
| S63  | 1.040 | 0.133 | 1.040 | 0.133 | N |
| S635 | 1.040 | 0.133 | 1.040 | 0.133 | N |
| S66  | 2.500 | 0.060 | 2.500 | 0.060 | N |
| S667 | 2.500 | 0.060 | 2.500 | 0.060 | N |
| T    | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T0   | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T05  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T054 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T055 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T1   | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T10  | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T101 | 0.390 | 0.067 | 0.390 | 0.067 | P |
| T105 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T106 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T107 | 0.910 | 0.080 | 0.910 | 0.080 | P |
| T108 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T17  | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T178 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T2   | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T20  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T208 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T3   | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T38  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T389 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T5   | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T50  | 0.160 | 0.054 | 0.160 | 0.054 | P |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| T504 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T59  | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T598 | 0.160 | 0.054 | 0.160 | 0.054 | P |
| T9   | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T90  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T907 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T92  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T929 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T94  | 0.250 | 0.061 | 0.250 | 0.061 | P |
| T944 | 0.250 | 0.061 | 0.250 | 0.061 | P |
| V    | 0.590 | 0.008 | 0.020 | 0.008 | N |
| V0   | 2.250 | 0.090 | 2.250 | 0.080 | N |
| V07  | 2.250 | 0.090 | 2.250 | 0.080 | N |
| V077 | 2.250 | 0.090 | 2.250 | 0.080 | N |
| V2   | 1.900 | 0.200 | 2.000 | 0.260 | N |
| V29  | 1.900 | 0.200 | 2.000 | 0.260 | N |
| V295 | 1.900 | 0.200 | 2.000 | 0.260 | N |
| V4   | 0.590 | 0.008 | 0.020 | 0.008 | N |
| V40  | 0.880 | 0.065 | 0.880 | 0.065 | N |
| V401 | 0.880 | 0.065 | 0.880 | 0.065 | N |
| V41  | 0.590 | 0.030 | 0.020 | 0.020 | N |
| V411 | 0.590 | 0.057 | 0.590 | 0.057 | N |
| V418 | 0.790 | 0.030 | 0.020 | 0.020 | N |
| V44  | 0.800 | 0.008 | 0.800 | 0.008 | N |
| V441 | 0.880 | 0.065 | 0.880 | 0.065 | N |
| V442 | 0.800 | 0.080 | 0.800 | 0.080 | N |
| V443 | 0.880 | 0.065 | 0.880 | 0.065 | N |
| V448 | 0.870 | 0.008 | 0.870 | 0.008 | N |
| V7   | 2.270 | 0.068 | 2.270 | 0.068 | N |
| V79  | 2.270 | 0.068 | 2.270 | 0.068 | N |
| V795 | 2.270 | 0.068 | 2.270 | 0.068 | N |
| V9   | 0.590 | 0.008 | 0.590 | 0.008 | N |
| V91  | 0.750 | 0.015 | 0.750 | 0.015 | N |
| V915 | 0.780 | 0.015 | 0.780 | 0.015 | N |
| V918 | 0.750 | 0.020 | 0.750 | 0.020 | N |
| V94  | 0.600 | 0.060 | 0.600 | 0.060 | N |
| V941 | 0.600 | 0.060 | 0.600 | 0.060 | N |
| V96  | 0.590 | 0.057 | 0.590 | 0.057 | N |
| V961 | 0.590 | 0.057 | 0.590 | 0.057 | N |
| V962 | 0.840 | 0.065 | 0.840 | 0.065 | N |
| V97  | 0.590 | 0.008 | 0.590 | 0.008 | N |
| V971 | 0.590 | 0.057 | 0.590 | 0.057 | N |
| V972 | 0.840 | 0.065 | 0.840 | 0.065 | N |
| V973 | 0.840 | 0.065 | 0.840 | 0.065 | N |
| V975 | 0.790 | 0.062 | 0.790 | 0.062 | N |
| V976 | 1.550 | 0.080 | 1.550 | 0.080 | N |
| V977 | 1.550 | 0.080 | 1.550 | 0.080 | N |

|      |       |       |       |       |   |
|------|-------|-------|-------|-------|---|
| V978 | 0.820 | 0.008 | 0.820 | 0.008 | N |
|------|-------|-------|-------|-------|---|

Legal Disclaimer: Any actions taken in reliance on or pursuant to this document are subject to Railinc's Terms of Use, as set forth in <https://public.railinc.com/terms-use>, and all AAR rules.